

In the drawings

FIG 3

FIG 3 has been replaced, and is corrected in the following manner:

1. Reference line has been redrawn to indicate that reference numeral 3250 refers to the lip of the top member, wherein the lip 3250 has a hole 3270 to receive the bolt of a lock.
2. Reference line has been redrawn to indicate that reference numeral 3150 refers to the lip of the bottom member, wherein the lip 3150 has a hole 3270 to receive the bolt of the lock received by the lip 3250 of the top member.
3. A reference number 3220 plus indicating line have been drawn to show the hole in the top member receiving the hitch bolt secured by the device.

FIG 5


FIG 5 has been replaced and is corrected to show reference numeral 5270 referring to the hole in lip of the top member, the hole 5270 receiving the bolt of a lock.

EXPRESS MAILING LABEL: _____
DATE OF DEPOSIT: 3-17-2005

COMMENTS

In the Office Action, the Examiner has noted the application is in condition for allowance, provided the specification is amended as above. Therefore, the application is in condition for allowance.

Respectfully submitted



David E. Orr
Registration No. 44,988
4619 NE 39nd Avenue
Vancouver, Washington 98661-2508